# U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION REPORT

# EPA Region 5 Records Ctr.

#### HEADING I.

December 7, 1995 Date:

American Plating Chicago, Cook County, Illinois. Subject:

Sam Borries, Region 5 U.S. EPA On-Scene Coordinator From:

Terri Johnson, OSWER (703) 603-9116 To:

Rick Karl, EERB (312) 353-9176

H. Valetkevitch, OPA (312) 353-1155

Don Bruce, EERB (312) 353-9176 Bill Messenger, EERB (312) 353-9176 Rich Clarizio, ORC (312) 886-0747 Joe Schuessler, CDOE (312) 744-6451

U.S. Fish and Wildlife Service, Illinois U.S. Coast Guard District 9 (216) 522-2738

Tom Crause, IEPA (217) 782-3258

#### POLREP # 6

S INKER!

#### II. BACKGROUND

Delivery Order No: 5001-05-379 Site No: VF

ERNS No: N/A CERCLIS NO: N/A

Response Authority: CERCLA NPL Status: Non-NPL State Notification: IEPA Start Date: 10/16/95 Demobilization Date: N/A Completion Date: N/A

Status of Action Memorandum: Approved on September 26, 1995.

## KII. SITE DESCRIPTION

- Incident Category: CERCLA
- Site Location: 1820 West Lake Street В. Chicago, Cook County, Illinois
  - Site description: The American Plating site is an 1. inactive and abandoned electroplating facility located at 1820 West Lake Street in Chicago, Cook County, Illinois. The site is situated in a mixed residential and commercial surrounding. The Henry Horner housing projects are located to the south across Lake Street. The site comprises of 6 large rooms and occupies approximately 0.5 acres. The coordinates for the site are latitude 41°53'8" North and longitude 87°40'18" The building is severely deteriorated and has a weak structural integrity with collapsed roofs at several locations. Entrance doors to the site are missing at several locations and free access to the

site exists. The site area is frequented by vagrants and a lot of "drug" paraphernalia is visible throughout the building.

2. Description of threat: Ecology & Environment, Inc. (E & E), the U.S. EPA Technical Assistance Team (TAT) contractor, conducted a site assessment in August 1995 and found chromic acid (Ph 1.58 units) in 1 vat, a 0.48 Ph acid in a drum labelled "sulfuric acid", a spilled drum containing 54,000 mg/kg chromium (TCLP chromium 608 mg/L), and a pit containing TCLP lead concentration of 5.2 mg/L. The open vats with hazardous contaminants, and several drums and pits with hazardous contaminants posed a threat to human health and the environment.

There have been at least 2 fires inside the building. The most recent fire occurred over the week of October 14, 1995. There were also two stolen/stripped vehicles inside the building since the site walk through October 3, 1995.

C. <u>Preliminary Assessment/Site Inspection Results</u> The American Plating site has not been previously evaluated under the Preliminary Assessment/Site Inspection investigative phases.

The site was brought to U.S. EPA's attention by the Chicago Department of Environment (CDOE), who investigated the site and found hazardous contaminants.

# IV. RESPONSE INFORMATION

# A. Situation

HP 1 1

- 1. Current situation: Weather conditions: High temperatures ranged from low 20s to low 40s. Periods of rain and snow flurries at times during the week. Rain/snow continues to hamper work as crew deals with slippery surfaces and muddy ground. Working hour site security necessary due to high crime area where site is located.
- 2. Removal activities to date: U.S. EPA initiated a removal action on October 16, 1995 by mobilizing the Emergency Response Cleanup Services (ERCS) contractor Smith Environmental and the TAT contractor E & E. Due to past vandalism and trespass at the site and the high crime neighborhood, armed security guards were hired to provide site security. The site building is screened daily with the help of the security guards. A Bobcat uniloader, a track mini-excavator, a storage trailer, and a mobile office trailer were mobilized to site.

During the last 2 weeks, completed removal of contaminated soil/sludge and wood debris from Pit #1 and stockpiled in Room #2. Loaded approximately 30 cubic yards (2 truckloads) of hazardous waste solids from Room #5 stockpile into roll-off boxes for off-site disposal. Steam cleaned Room #2 (including Pit #1), Room #3, Room #4, Room #5, and Room #6 using power washer. Placed snow fence barriers around Pits #1 and #2 and all entrances to building to restrict site access. Received analytical data for Vat #5 liquids (after treatment) and Pit #1 sludge and debris. results revealed material as non hazardous. results of composite samples from East Wall/Room #4, Walls and Floors/Room #3, and North and South sections of Pit #2/Room #5 revealed all material as non hazardous, except for TCLP chromium levels on East Wall in Room #4. The East Wall in Room #4 was further decontaminated and resampled by TAT. Pumped neutralized residual liquids in Vat #5 into drums. Finished dismantling wood vat platforms and metal Vats #2, #3, #4, and #5. Shipped out 3 empty decontaminated Disposed of small box of infectious wastes to off-site disposal facility in Germantown, Wisconsin. Conducted general site cleanup. TAT performed air monitoring inside Pit #1 in Room #2 with no levels above background recorded on oxygen/explosimeter.

3. **Enforcement:** 104(e) Notification Letters have been sent to all of the known site Potentially Responsible Parties (PRPs).

# B. Planned Removal Actions

Sample all site waste streams and arrange for waste disposal. Clear and sweep all areas. Remove and consolidate all waste materials in drums, vats, pits, walls, and floors. Decontaminate necessary portions of the building.

# C. Next Steps

Complete disposal of drums and Room #3 debris and soil. Decontaminated all remaining floors.

# D. Rey Issues

Decontamination of the building: Various alternatives are being considered for proper decontamination, however few will possibly remain within budget constraints while ensuring worker safety. Most of the alternatives will limit or disallow complete decontamination.

### V. COSTS

## Extramural Costs:

| Total Cleanup Contractor (e.g,      |                  |
|-------------------------------------|------------------|
|                                     | \$ 145,235.31    |
| IAGs                                | \$ 0.00          |
| Cooperative Agreements/Letter       | Contracts\$ 0.00 |
| TAT/START                           | \$ 8,312.00      |
| CLP                                 | \$ 0.00          |
| REAC                                | \$ 0.00          |
| TOTAL, EXTRAMURAL COSTS             | \$ 153,547.31    |
| Intramural Costs:                   |                  |
| Direct Costs (Region, HQ, ERT)      |                  |
| Intramural Indirect Costs           | \$ 14,007.10     |
| TOTAL, INTRAMURAL COSTS             | \$ 21,942.10     |
| TOTAL SITE COST                     | \$ 175,489.41    |
| Project Ceiling                     | \$ 323,000.00    |
| Project Funds Remaining (percentage |                  |

The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor. Other financial data, which the OSC must rely upon, may not be entirely up to date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

# VI. DISPOSITION OF WASTES

Mastestream Medium Quantity Containment Treatment Disposal

Non-haz debris Solid 80 cu.yds. Roll-off box Hegewisch Landfill Landfill

Haz waste solid Solid 150 cu.yds.Roll-off box City Envir. Landfill Landfill

Waste corr. liq. Liquid 4,100 gals. Tanker Dynecol, Inc. Treatment

Infectious waste Solid sm. bag cardboard box Environ. Guardian Incineration

Haz waste solid Solid 30 cu.yds.Roll-off box City Envir. Landfill Landfill